

1 / 2




FIG. 1






FIG. 2



100

NO STICKING OR WETTING
OF UPPER SURFACE


FIG. 3A



90

SLIGHT RANDOM STICKING OR
WETTING OF UPPER SURFACE


FIG. 3B



80

WETTING OF UPPER SURFACE
AT SPRAY POINTS


FIG. 3C



70

PARTIAL WETTING OF WHOLE
UPPER SURFACE ONLY


FIG. 3D



50

COMPLETE WETTING OF WHOLE
OF UPPER SURFACE ONLY

FIG. 3E



0

COMPLETE WETTING OF WHOLE OF
UPPER AND LOWER SURFACES

FIG. 3F